LAMPIRAN

A.	Radiographic Inspection Report Joint 4	60
B.	Radiographic Inspection Report Joint 8	61
C.	Radiographic Inspection Report Joint 11	62
D.	Radiographic Testing Procedure UTI-OPR-00-2014-RT	63
E.	Welding &Welding Repair Procedure	72
F.	Welding Procedure Specification (WPS)	81
G.	Procedure Qualification Record	83
H.	Design Joint 4 ISO-27	85
I.	Design Joint 8 ISO-21	86
J.	Design Joint 11 ISO-25	87

