

DAFTAR GAMBAR

Gambar 1.1 <i>Flow Chart</i> Metode Kerja Praktek	5
Gambar 2.1 Logo PT. TORAY	7
Gambar 2.2 Lokasi PT. Indonesia Toray Synthetics	9
Gambar 2.3 Layout Lokasi PT. Indonesia Toray Synthetics.....	10
Gambar 2.4 Struktur Organisasi PT. Indonesia Toray Synthetics.....	12
Gambar 2.5 Diagram Alir Proses Produksi Chip Film PT. Indonesia Toray Synthetics.....	16
Gambar 2.6 Reaksi Esterifikasi	18
Gambar 3.1. Check Sheet	24
Gambar 3.2. Diagram Batang	25
Gambar 3.3. Diagram Pareto	25
Gambar 3.4. Diagram <i>Cause and Effect</i>	26
Gambar 3.5. Peta Kendali X.....	27
Gambar 3.6. Peta Kendali R	28
Gambar 4.1 <i>Pareto Chart Defect</i> pada produk <i>Chip E900</i>	33
Gambar 4.3 Peta Kendali P dengan menggunakan Minitab.....	35
Gambar 4.4 Diagram <i>Fishbone</i> penyebab <i>Defect Haze</i> pada <i>Chip E900</i>	36

UNIVERSITAS
MERCU BUANA