

## DAFTAR GAMBAR

Gambar 1. 1 Jumlah <i>Defect</i> Oktober – Februari 2020 .....	2
Gambar 2. 1 Bentuk Diagram SIPOC .....	5
Gambar 2. 2 Diagram Pareto ( <i>Pareto Chart</i> ) .....	8
Gambar 2. 3 Diagram Sebab Akibat .....	9
Gambar 2. 4 Diagram Sebab Akibat .....	11
Gambar 2. 5 Check Sheet (Lembar Pemeriksaan ) .....	12
Gambar 2. 6 Diagram Pareto ( <i>Pareto Chart</i> ) .....	13
Gambar 2. 7 Histogram .....	13
Gambar 2. 8 Diagram Pencar ( <i>Scatter Diagram</i> ) .....	14
Gambar 2. 9 Peta Kendali ( <i>Control Chart</i> ) .....	15
Gambar 2. 10 Diagram Proses ( <i>Flow Chart</i> ) .....	16
Gambar 3. 1 Langkah-langkah Penelitian .....	38
Gambar 4. 1 Lambang PT. Sukses Abadi Farmino .....	41
Gambar 4. 2 Struktur Organisasi .....	43
Gambar 4. 3 <i>Layout</i> Perusahaan .....	48
Gambar 4. 4 Alur proses produksi Nexx Gingseng Coffee .....	49
Gambar 4. 5 Jenis <i>defect</i> Coding .....	51
Gambar 4. 6 Jenis <i>defect</i> Potongan Seal .....	52
Gambar 4. 7 Jenis <i>defect</i> Bobot Produk .....	52
Gambar 4. 8 Jenis <i>defect</i> Bolong .....	53
Gambar 4. 9 SIPOC Produk Nexx Gingseng Coffee .....	57
Gambar 4. 10 Diagram Pareto .....	72
Gambar 4. 11 <i>Fishbone Diagram</i> .....	73
Gambar 4. 12 Mesin <i>filling</i> AST MPV- 10PS .....	76
Gambar 4. 13 Mesin <i>filling</i> DXDF-150 .....	77