

DAFTAR GAMBAR

	Halaman
Gambar 1.1 Grafik Pareto Jumlah <i>Defect</i> periode bulan Desember 2019 sampai Juni 2020	2
Gambar 2.1 Contoh Lembar Periksa (<i>Checksheets</i>).....	17
Gambar 2.2 Contoh Stratifikasi	18
Gambar 2.3 Contoh Histogram	19
Gambar 2.4 Contoh Diagram Pareto.....	20
Gambar 2.5 Contoh Diagram <i>Fishbone</i>	22
Gambar 2.6 Contoh Diagram Tabur	23
Gambar 2.7 Contoh Peta Kendali	24
Gambar 2.8 Kerangka Pemikiran	30
Gambar 3.1 Langkah-Langkah Penelitian.....	37
Gambar 4.1 Bangunan Pabrik.....	38
Gambar 4.2 Struktur Organisasi PT. Subang <i>Autocomp</i> Indonesia.....	40
Gambar 4.3 Peta Proses Operasi <i>Wiring Harness</i>	41
Gambar 4.4 Proses <i>Material Supply</i>	41
Gambar 4.5 Proses <i>Automatic Cutting</i>	42
Gambar 4.6 Proses <i>Inspection</i>	42
Gambar 4.7 Proses <i>Sub Assy</i>	42
Gambar 4.8 Proses <i>Setting</i>	43
Gambar 4.9 Proses <i>Taping</i>	43
Gambar 4.10 Proses <i>Electrical Test</i>	43
Gambar 4.11 Proses <i>Part Detection</i>	44
Gambar 4.12 Proses <i>Visual Inspection</i>	44
Gambar 4.13 Proses <i>Finish Goods</i>	44
Gambar 4.14 Grafik Jumlah <i>Defect</i> Periode Bulan Desember 2019 sampai Juni 2020.....	46
Gambar 4.15 Grafik <i>Pareto Chart</i> Jenis <i>Defect Wire Instrument Panel</i>	49
Gambar 4.16 Grafik Peta Kendali P	51

Gambar 4.17 Hasil FGD Penyebab <i>Defect</i>	52
Gambar 4.18 Diagram Sebab Akibat <i>Cross Circuit</i>	54
Gambar 4.19 Diagram Sebab Akibat <i>Wrong Dimension</i>	55
Gambar 4.20 Grafik <i>Pareto Chart</i> RPN	59
Gambar 5.1 Holder Kendor/Geser	63
Gambar 5.2 Clip Tidak Masuk Pada <i>Holder</i>	64
Gambar 5.3 Diagram Sakihame Rusak	64
Gambar 5.4 Penempatan <i>Similar Circuit</i> Berdekatan.....	65
Gambar 5.5 Hasil FGD Usulan Perbaikan	66
Gambar 5.6 Patroli Harian Pengecekan <i>Equipment</i>	68
Gambar 5.7 Pemberian <i>Lisence</i> Untuk Operator.....	69
Gambar 5.8 Penambahan Program Navigasi.....	69
Gambar 5.8 Penempatan <i>Similar Circuit</i> Dijauhkan	70
Gambar 5.9 Grafik Perbedaan <i>Gap Total Defect</i> Sebelum dan Sesudah Perbaikan.....	75
Gambar 5.10 Grafik Perbedaan <i>Gap</i> Berdasarkan Jenis <i>Defect</i> Debelum dan Sesudah Perbaikan.....	75