

DAFTAR GAMBAR

	Halaman
Gambar 1.1 <i>APU Shop Visit Summary 2019</i>	3
Gambar 2.1 Kegiatan Pemeliharaan	8
Gambar 2.2 APU GTCP131-9[A]	9
Gambar 2.3 <i>APU Cross Section</i>	10
Gambar 2.4 Siklus DMAIC.....	16
Gambar 2.5 Siklus PDCA	26
Gambar 2.6 Kerangka Pemikiran	32
Gambar 3.1 Langkah-Langkah Penelitian.....	37
Gambar 4.1 Struktur Organisasi PT. GMF Aeroasia Tbk.....	40
Gambar 4.2 <i>Pareto Chart</i> Jenis Kerusakan APU	44
Gambar 4.3 Diagram <i>Fishbone</i> Kerusakan APU	47
Gambar 4.4 <i>Training Attendance List</i> GMF Oktober 2019	53
Gambar 4.5 Upgrade <i>Manual Torque</i> ke <i>Setting Value Torque</i>	55
Gambar 4.6 <i>Engine Defect Investigation Report</i>	56
Gambar 4.7 Beberapa <i>defect</i> yang ditemukan.....	58
Gambar 4.8 Pergantian Komponen <i>Seal Air/Oil Stationary</i>	60
Gambar 4.9 <i>Workscope APU GTCP131-9[A] after finding defect-1</i>	61
Gambar 4.10 <i>Workscope APU GTCP131-9[A] after finding defect-2</i>	62
Gambar 4.11 <i>Failure Mode for Smoke at Exhaust</i>	65