

## DAFTAR TABEL

Tabel 1. 1 Komponen mobil YHA (Ertiga) .....	2
Tabel 1. 2 <i>Defect Garnish Back Door License</i> bulan April 2018-Januari 2019 .....	3
Tabel 2. 1 Jenis peta kendali .....	9
Tabel 2. 2 Langkah implementasi VSM .....	12
Tabel 2. 3 Tingkat Kualitas Sigma Yield.....	15
Tabel 2. 4 Nilai <i>severity, occurance, dan detection</i> .....	18
Tabel 2. 5 Penelitian Terdahulu .....	19
Tabel 4. 1 Data Jumlah <i>Defect Part Garnish Back Door License</i> Januari 2019... ..	40
Tabel 4. 2 Waktu Proses Mesin A02 <i>Injection Molding</i> .....	41
Tabel 4. 3 CTQ <i>Part Garnish Back Door License</i> .....	49
Tabel 4. 4 <i>Current State Map</i> .....	50
Tabel 4. 5 Peta kendali p .....	54
Tabel 4. 6 Revisi peta kendali p .....	55
Tabel 4. 7 DPMO dan SQL <i>Garnish Back Door License</i> Januari 2019 .....	57
Tabel 4. 8 Hasil perhitungan <i>yield</i> .....	58
Tabel 4. 9 <i>Future State Map</i> .....	60
Tabel 4. 10 FMEA <i>defect silver streak</i> .....	62
Tabel 4. 11 Hasil dan Pembahasan .....	67