

DAFTAR GAMBAR

Gambar 1.1 Data <i>Defect</i> produk CHC bulan Januari – Agustus 2019	2
Gambar 2.1 Lembar Pemeriksaan	13
Gambar 2.2 Diagram Sebar	14
Gambar 2.3 Diagram Sebab Akibat.....	15
Gambar 2.4 Diagram Pareto	16
Gambar 2.5 Diagram Alir atau Diagram Proses.....	17
Gambar 2.6 Histogram	17
Gambar 2.7 Peta Kendali.....	18
Gambar 2.8 Kerangka Pemikiran	27
Gambar 3.1 Tahapan Penelitian	35
Gambar 4.1 Logo perusahaan.....	36
Gambar 4.2 Peta Lokasi PT. Toyota Boshoku Indonesia.....	37
Gambar 4.3 Struktur Organisasi Perusahaan.....	39
Gambar 4.4 Produk TBINA	40
Gambar 4.5 <i>Flow Process</i> Produksi CHC	41
Gambar 4.11 Grafik peta kendali P-Chart.....	48
Gambar 4.7 Diagram Pareto	49
Gambar 4.8 Cacat Jenis <i>Blowpipe Burry</i>	49
Gambar 4.9 Cacat Jenis <i>Stamp Part Number Blur</i>	50
Gambar 4.12 Fishbone Diagram Problem <i>Blowpipe Burry</i>	51
Gambar 4.13 <i>Pin dan Bottom Aus</i>	53

Gambar 4.14 <i>Pin dan Bottom Tidak Center</i>	54
Gambar 4.15 Operator Produksi Mengecek area <i>Blowpipe</i>	54
Gambar 4.16 <i>Fishbone Diagram Problem Stamp Part Number Blur</i>	56
Gambar 4.17 <i>Stopper Box</i>	57
Gambar 4.18 Proses <i>Stamp Part Number</i>	58

