

## DAFTAR GAMBAR

Gambar 1.1. Diagram Grafik <i>PPm</i> Periode Januari 2019 – Juni 2019 .....	2
Gambar 2.1. Contoh Diagram Pareto.....	8
Gambar 2.2. Contoh Diagram <i>Fishbone</i> .....	10
Gambar 2.3. <i>8 Steps PDCA Problem Solving</i> .....	12
Gambar 2.4. Kerangka Pemikiran.....	18
Gambar 3.1 Diagram Alir Penelitian .....	25
Gambar 4.1 Tampilan Depan PT. MW .....	28
Gambar 4.2 Denah Lokasi <i>Room Quality Control</i> PT. MW .....	30
Gambar 4.3 Struktur Organisasi <i>QC Line Stamping</i> .....	31
Gambar 4.4 Material SPCC 2.0 x 1219 x 4238 .....	32
Gambar 4.5 Material SPHC 3.2 x 45 x 1219 .....	33
Gambar 4.6 Mesin <i>Cutting</i> .....	33
Gambar 4.7 Mesin <i>Stamping</i> 80 Ton .....	34
Gambar 4.8 Mesin <i>Stamping</i> 60 Ton .....	34
Gambar 4.9 Mesin <i>Stamping</i> 45 Ton .....	34
Gambar 4.10 <i>Flow Process Chart Washer Clevis</i> .....	38
Gambar 4.11 Produk <i>Washer Clevis</i> .....	40
Gambar 4.12 Jenis <i>Defect Washer Clevis</i> .....	43
Gambar 5.1 Diagram Pareto Jenis <i>Defect Washer Clevis</i> .....	46
Gambar 5.2 Target Penurunan <i>Defect Washer Clevis</i> .....	48
Gambar 5.3 Diagram <i>Fishbone Defect Washer Clevis</i> .....	49
Gambar 5.4 Keadaan <i>Part</i> Sebelum dan Sesudah Perbaikan .....	52
Gambar 5.5 Keadaan <i>Dies</i> Sebelum dan Sesudah Perbaikan .....	53
Gambar 5.6 Alat Bantu <i>Jig Inspection</i> .....	54
Gambar 5.7 <i>Q Point</i> Produk <i>Washer Clevis</i> .....	55

