

DAFTAR GAMBAR

Gambar 1.1 Pareto Diagram Problem Tunas Toyota Bintaro BP	2
Gambar 1.2 <i>Brake Down Re-do Paint</i> Berdasarkan Jenis Pekerjaan	3
Gambar 1.3 <i>Brake Down Re-do Paint</i> Berdasarkan <i>Defect</i> dari factor <i>Man & Machine</i>	3
Gambar 1.4 <i>Parking Over Flow</i> menghalangi pintu masuk penerimaan	4
Gambar 1.5 <i>Parking Over Flow</i> menutup jalan keluar masuk kendaraan	4
Gambar 2.1 Foto Tunas Toyota Bintaro <i>Body & Paint</i>	7
Gambar 2.2 Profile Tunas Toyota Bintaro <i>Body & Paint</i>	8
Gambar 2.3 Konsep Siklus <i>PDCA</i>	10
Gambar 2.4 <i>New Eight Step Improvement Flow Process</i>	10
Gambar 2.5 <i>Pareto Diagram</i>	16
Gambar 2.4 Contoh gambar <i>Spray Booth Blowtherm</i>	18
Gambar 2.5 Contoh Gambar <i>Spray Gun</i>	19
Gambar 4.1 <i>Fishbone Diagram</i>	24
Gambar 4.2 <i>Form Questionnaire</i>	27
Gambar 4.3 Pareto Diagram Hasil <i>Questionnaire</i>	28
Gambar 4.4 Target <i>Improvement</i>	30
Gambar 4.5 Implementasi <i>Process Multiskill Manpower</i>	31
Gambar 4.6 Stall khusus untuk <i>Process Multiskill Manpower</i>	32
Gambar 4.7 <i>Develop Training Man Power</i> oleh <i>Paint Maker</i>	33
Gambar 4.8 Penjadwalan <i>booking</i> pada <i>Job Schedule Control Board</i>	34
Gambar 4.9 Pemindahan ke <i>Job Process Control Board</i>	35

Gambar 4.10 <i>Maintenance Spray Booth dan Spray Gun</i>	35
Gambar 4.11 <i>Check Sheet Maintenance Spray Booth dan Spray Gun</i>	36
Gambar 4.12 <i>Evaluasi Redo Paint berdasarkan Breakdown Unit Entry</i>	36
Gambar 4.13 <i>Evaluasi Revenue Bengkel</i>	38
Gambar 4.14 <i>Evaluasi Unit Entry Bengkel</i>	39

