

DAFTAR GAMBAR

	Halaman
Gambar 1.1 Grafik OEE Mei 2018- Oktober 2018 dalam persen (%).....	3
Gambar 2.1 Sistem Implementasi TPM	12
Gambar 2.2 Metodologi OEE (<i>Overall Equipment Effectiveness</i>)	18
Gambar 2.3 <i>Six Big Losses</i> dan OEE	24
Gambar 2.4 <i>Fishbone Diagram</i>	25
Gambar 2.5 <i>Pareto Diagram</i>	25
Gambar 2.6 Kerangka Pemikiran.....	32
Gambar 3.1 Langkah-langkah Penelitian.....	37
Gambar 4.1 Kain Ban (<i>Tire Cord Fabric</i>)	41
Gambar 4.2 Filament.....	41
Gambar 4.3 Proses Produksi Kain Ban	42
Gambar 4.4 Gudang Material.....	43
Gambar 4.5 <i>Twisting Process</i>	43
Gambar 4.6 <i>Weaving Process</i>	44
Gambar 4.7 <i>Diping Process</i>	45
Gambar 4.8 Mesin Dornier 2706	47
Gambar 4.9 <i>Control Parameter</i>	48
Gambar 4.10 <i>Backrest Roll</i>	48
Gambar 4.11 <i>Felt Harness Guide</i>	49
Gambar 4.12 <i>Selvedge Sensor</i>	50
Gambar 4.13 <i>Scissor CPL</i>	51
Gambar 4.14 <i>Feeder ROJ</i>	51
Gambar 4.15 <i>Control Valve Device</i>	52
Gambar 4.16 <i>Tuck-in Motion</i>	52
Gambar 4.17 <i>Short stroke cylinder</i>	53
Gambar 5.1 Grafik Nilai OEE week 1-24	68
Gambar 5.2 <i>Pareto Diagram Six Big Losses</i>	70
Gambar 5.3 <i>Fishbone Diagram</i>	71
Gambar 5.4 Form validasi usulan perbaikan Motor driver	76
Gambar 5.5 Form validasi usulan perbaikan Kurang pengetahuan teknisi.....	77
Gambar 5.6 Form validasi usulan perbaikan Material cord terdapat flup.....	78
Gambar 5.7 Form validasi usulan perbaikan Teknisi dan <i>Setup</i> Lama.....	79