

DAFTAR GAMBAR

Gambar 2.1 <i>Total Productive Maintenance</i>	19
Gambar 2.2 Pilar TPM.....	21
Gambar 2.3 Mesin <i>Bending</i>	30
Gambar 2.4 Contoh Diagram Pareto.....	32
Gambar 2.5 Fishbone Diagram.....	33
Gambar 2.6 Kerangka Pemikiran Penelitian.....	38
Gambar 3.1 Diagram Alir Penelitian.....	40
Gambar 3.2 Diagram Alir <i>Improvement</i>	43
Gambar 4.1 <i>Flow Chart Con Sub Assy</i>	48
Gambar 4.2 Diagram <i>Pareto Six Big Losses</i>	75
Gambar 4.3 Histogram Data <i>No Good</i> Periode 22 Juli - September 2019.....	78
Gambar 4.4 Pareto Data <i>No Good</i> Periode Juli-September 2019.....	78
Gambar 4.5 <i>Unfinish Process</i>	79
Gambar 4.6 <i>Scratch</i>	79
Gambar 4.7 <i>Angle No Good (NG)</i>	79
Gambar 4.8 Penentuan Target.....	80
Gambar 4.9 Analisa Kondisi Yang Ada.....	81
Gambar 4.10 <i>Fishbone Diagram Unfinish Process</i>	82
Gambar 4.11 Kondisi Sebelum <i>Improvement</i>	84
Gambar 4.12 Parameter Data Servo.....	84
Gambar 4.13 Kondisi <i>Program PLC</i> Sebelum <i>Improvement</i>	85
Gambar 4.14 Kondisi <i>Program PLC</i> Setelah <i>Improvement</i>	86
Gambar 4.15 Kondisi 1 <i>Cycle</i> Mesin OK.....	86
Gambar 4.16 Kondisi Nilai <i>Auto Tune Response</i> Original.....	87
Gambar 4.17 Kondisi Nilai <i>Auto Tune Response</i> baru.....	87
Gambar 4.18 Kondisi Mesin <i>Bending</i> saat terjadi kegagalan <i>Interlock</i>	88
Gambar 4.19 Kondisi Mesin <i>Bending</i> saat <i>Interlock OK</i>	89



UNIVERSITAS
MERCU BUANA