

DAFTAR GAMBAR

No. Gambar		Halaman
1.1	Kantor Perusahaan	1
1.2	Logo Perusahaan	2
1.3	Lokasi Perusahaan	3
1.4	Struktur Organisasi Perusahaan	5
3.1	Proses singkat kerja mesin laser cutting	11
3.2	Mesin utama HSG HS-TS65	12
3.3	Numerical Control Pneumatic Chuck	13
3.4	Komponen IPG 2.000watt – 20.000wat	13
3.5	Industrial Chiller CW-6000	14
3.6	Precitec Head Laser Jerman dan Kabel Fiber IPG Photonics	14
3.7	Nozzle Laser Head IPG Photonics	15
3.8	Lens Focus Laser Head IPG Photonics	15
4.1	Hasil Cacat atau NG material Stainless Steel	25
4.2	Hasil Cacat atau NG material Mild Steel	26
4.3	Penyebab masalah hasil potongan	27
4.4	Diagram Sebab Akibat Fishbone	27
4.5	Lensa dan Nozzle yang sudah rusak	31
4.6	Hasil OK pada material Mild Steel dan Stainless Steel	32