

DAFTAR GAMBAR

Gambar 1.1. Gedung PT. Putranata Adi Mandiri	3
Gambar 1.2. Lokasi PT. Putranata Adi Mandiri	3
Gambar 1.3. Logo perusahaan	4
Gambar 1.4. Struktur organisasi PT.Putranata Adi Mandiri	5
Gambar 3.1. Siklus getaran	11
Gambar 3.2. Standart ISO 10816-3	14
Gambar 3.3. Centrifugal fan	15
Gambar 3.4. Axial fan	16
Gambar 3.5. <i>Force unbalance</i>	17
Gambar 3.6. <i>Couple unbalance</i>	18
Gambar 3.7. <i>Dynamic unbalance</i>	18
Gambar 3.8. <i>Overhung unbalance</i>	19
Gambar 3.9. Jenis <i>unbalance</i>	19
Gambar 4.1. Diagram alir	23
Gambar 4.2. Pemasangan taco meter	25
Gambar 4.2. <i>Spectrum</i> sebelum <i>balancing</i>	26
Gambar 4.3. Penambahan <i>trial weight</i> sudut 0°	27
Gambar 4.4. <i>Centrifugal fan</i> VR72-2000	28
Gambar 4.5. Penambahan <i>correction weight</i> sudut 306°	28
Gambar 4.6. <i>Spectrum</i> sesudah <i>balancing</i>	30