

DAFTAR GAMBAR

Gambar 1.1. Gedung PT. Putranata Adi Mandiri	3
Gambar 1.2. Lokasi PT. Putranata Adi Mandiri	3
Gambar 1.3. Logo Perusahaan	4
Gambar 1.4. Struktur Organisasi PT. Putranata Adi Mandiri	5
Gambar 3.1. Gelombang getaran pegas	10
Gambar 3.2. Karakteristik getaran	11
Gambar 3.3. <i>Force unbalance</i>	13
Gambar 3.4. <i>Couple unbalance</i>	13
Gambar 3.5. <i>Dynamic unbalance</i>	13
Gambar 3.6. <i>Overhug unbalance</i>	14
Gambar 3.7. <i>Angular misalignment</i>	15
Gambar 3.8. <i>Paralel misalignment</i>	15
Gambar 3.9. <i>Bearing and pulley misalignment</i>	16
Gambar 3. 10. <i>Bent shaft</i> aksial	16
Gambar 3. 11. <i>Bent shaft</i> horizontal	16
Gambar 3.12. Spektrum kerusakan <i>roller bearing</i>	17
Gambar 3.13. Spektrum <i>sleeve bearing</i>	18
Gambar 3.14. <i>Oil whirl</i>	18
Gambar 3.15. Spektrum kerusakan <i>drive belt</i>	19
Gambar 3.16. <i>Looseness</i>	19
Gambar 3.17. Rotor spektrum	20
Gambar 3.18. <i>Aerodynamic</i> spektrum	21
Gambar 3.19. Arah pengukuran vibrasi	22
Gambar 3.20. ISO-10816	23
Gambar 4.1. Diagram Alir	25
Gambar 4.2. <i>Centrifugal fan</i>	27
Gambar 4.3. Sinyal geratan motor <i>outboard</i> horizontal	28
Gambar 4.4. Sinyal geratan motor <i>outboard</i> vertikal	29
Gambar 4.5. Sinyal geratan motor <i>inboard</i> horizontal	29
Gambar 4.6. Sinyal geratan motor <i>inboard</i> vertikal	30
Gambar 4.7. Sinyal geratan <i>fan inboard</i> horizontal	30

Gambar 4.8. Sinyal geratan <i>fan inboard</i> vertikal	31
Gambar 4.9. Sinyal geratan <i>fan inboard</i> aksial	31
Gambar 4.10. Sinyal geratan <i>fan ouboard</i> horizontal	32
Gambar 4.11. Sinyal geratan <i>fan ouboard</i> vertikal	32
Gambar 4.12. Sinyal geratan <i>fan ouboard</i> aksial	33

