

DAFTAR GAMBAR

Gambar 4.1 Lokasi Site Proyek.....	27
Gambar 4.2 Lokasi Site Proyek.....	28
Gambar 4.3 Denah Lantai Satu.....	29
Gambar 4.4 Denah Lantai Mezzanine	30
Gambar 4.5 Denah Lantai Dua	31
Gambar 4.6 Denah Dak Atap	32
Gambar 4.7 Detail Pondasi Tiang Pancang	34
Gambar 4.8 Detail Pondasi Tiang Pancang	35
Gambar 4.9 Detail Pencanaan Kolom	37
Gambar 4.10 Detail Pencanaan Kolom	37
Gambar 4.11 Detail Pencanaan Kolom	37
Gambar 4.12 Detail Pencanaan Kolom	38
Gambar 4.13 Detail Pencanaan Balok	39
Gambar 4.14 Detail Pencanaan Balok	40
Gambar 4.15 Detail Pencanaan Balok	40
Gambar 4.16 Detail Pencanaan Balok	40
Gambar 4.17 Detail Pencanaan Balok	41
Gambar 4.18 Detail Pencanaan Balok	41
Gambar 4.19 Detail Pencanaan Plat	42
Gambar 4.20 Struktur Organisasi Proyek.....	44
Gambar 4.21 Jack In Pilet	46
Gambar 4.22 Truck Mixer.....	47
Gambar 4.23 Concrete Pump	47
Gambar 4.24 Scaffolding	48
Gambar 4.25 Panel Listrik.....	48
Gambar 4.26 Lampu HPIT	48
Gambar 4.27 Gerobak Proyek	49
Gambar 4.28 Sepatu Proyek.....	49
Gambar 4.29 Helm dan Topi	49

Gambar 4.30 Sarung Tangan.....	50
Gambar 4.31 Meteran	50
Gambar 4.32 Palu	50
Gambar 4.33 Cangkul	51
Gambar 4.34 Sekop dan Sekop Semen	51
Gambar 4.35 Roskam	51
Gambar 4.36 Selang Air.....	52
Gambar 4.37 Tong/Tempat Air.....	52
Gambar 4.38 Beton Ready Mix	53
Gambar 4.39 Besi Tulangan	53
Gambar 4.40 Wiremesh	54
Gambar 5.1 Revisi Denah Titik Pancang.....	58
Gambar 5.2 Perubahan Perencanaan Tie Beam.....	60
Gambar 5.3 Pembesian Pile Cape dan Tie Beam.....	61
Gambar 5.4 Bekisting Pile Cape	61
Gambar 5.5 Bekisting Tie Beam.....	61
Gambar 5.6 Pengecoran Pile Cape dan Tie Beam.....	62
Gambar 5.7 Pekerjaan Bekisting Kolom.....	64
Gambar 5.8 Pengecoran Kolom Pedestal dan Pembongkaran Bekisting Kolom.....	65
Gambar 5.9 Pekerjaan Bekisting Balok.....	67
Gambar 5.10 Pekerjaan Pembesian Balok.....	68
Gambar 5.11 Pengecoran Balok	69
Gambar 5.12 Pekerjaan Plat Lantai Satu	70
Gambar 5.13 Bekisting Plat Lantai	71
Gambar 5.14 Pembesian Plat Lantai.....	72
Gambar 5.15 Pengecoran Plat Lantai	73
Gambar 5.16 Permasalahan Pelaksanaan Proyek.....	74