

DAFTAR GAMBAR

		Halaman
Gambar 1.1	Mesin <i>Die Casting dan Furnace Melting</i>	1
Gambar 1.2	Hasil Produksi <i>Parts Casting</i>	1
Gambar 1.3	<i>Cartridge Heater</i> kondisi baik	2
Gambar 1.4	<i>Cartridge Heater</i> kondisi rusak	2
Gambar 2.1	Prinsip Las TIG	8
Gambar 2.2	Mesin Las TIG dan Sistem Operasionalnya	9
Gambar 2.3	Elektroda Tungsten untuk pengelasan AC dan DC	11
Gambar 2.4	Penggunaan arus listrik <i>alternating current high frequency</i>	14
Gambar 2.5	Penggunaan arus listrik <i>Direct Current Straight Polarity</i>	15
Gambar 2.6	Penggunaan arus <i>Direct Current Reverse Polarity</i>	15
Gambar 2.7	<i>Iron Carbon Equilibrium Phase Diagram</i>	20
Gambar 2.8	<i>Nickel-Chromium Phase Diagram</i>	21
Gambar 3.1	Diagram alir pelaksanaan Penelitian	23
Gambar 3.2	Pengecekan tegangan pada mesin las	25
Gambar 3.3	Membersihkan material <i>sample</i> uji	25
Gambar 3.4	Penyambungan material <i>sample</i> uji dengan mengelas	25
Gambar 3.6	Pengamatan <i>Spesimen</i> yang telah dietsa pada Pengujian Metalografi	29
Gambar 3.7	Diagram alir Persiapan Struktur Makro dn Mikro	31
Gambar 3.8	Hasil Mounting <i>Sample Uji</i>	33
Gambar 3.9	Pengamatan kposisi kimia dengan EDAX	36
Gambar 4.1.1	Grafik Komposisi Kimia <i>Base Metal</i> kaki <i>heater</i>	37
Gambar 4.1.2	Grafik Komposisi Kimia <i>Base Metal coil heater</i>	38
Gambar 4.1.3	Grafik Komposisi Kimia Komposisi Kimia <i>Weld Metal</i>	39
Gambar 4.2.1	Penampang Las A1 (HT = 900° <i>celcius</i>)	40
Gambar 4.2.2	Penampang Las B1 (HT = 900° <i>celcius</i>)	40
Gambar 4.2.3	Penampang Las C1 (HT = 900° <i>celcius</i>)	40
Gambar 4.2.4	Penampang Las A2 (HT = 1000° <i>celcius</i>)	41
Gambar 4.2.5	Penampang Las B2 (HT = 1000° <i>celcius</i>)	41
Gambar 4.2.6	Penampang Las B2 (HT = 1000° <i>celcius</i>)	41

Gambar 4.2.7	Penampang Las A3 (HT = 1100° <i>celcius</i>)	42
Gambar 4.2.8	Penampang Las B3 (HT = 1100° <i>celcius</i>)	42
Gambar 4.2.9	Penampang Las C3 (HT = 1100° <i>celcius</i>)	42
Gambar 4.3.1	Daerah Haz 1 A (HT = NO)	43
Gambar 4.3.2	Daerah inti Las A (HT = NO)	43
Gambar 4.3.3	Daerah Haz 2 A (HT = NO)	43
Gambar 4.3.4	Daerah Haz 1 B (HT = NO)	44
Gambar 4.3.5	Daerah inti Las B (HT = NO)	44
Gambar 4.3.6	Daerah Haz 2 B (HT = NO)	44
Gambar 4.3.7	Daerah Haz 1 C (HT = NO)	45
Gambar 4.3.8	Daerah inti Las C (HT = NO)	45
Gambar 4.3.9	Daerah Haz 2 C (HT = NO)	45
Gambar 4.3.10	Daerah Haz 1 A1 (HT = 900° <i>celcius</i>)	46
Gambar 4.3.11	Daerah inti Las A1 (HT = 900° <i>celcius</i>)	46
Gambar 4.3.12	Daerah Haz 2 A1 (HT = 900° <i>celcius</i>)	46
Gambar 4.3.13	Daerah Haz 1 B1 (HT = 900° <i>celcius</i>)	47
Gambar 4.3.14	Daerah inti Las B1 (HT = 900° <i>celcius</i>)	47
Gambar 4.3.15	Daerah Haz 2 B1 (HT = 900° <i>celcius</i>)	47
Gambar 4.3.16	Daerah Haz 1 C1 (HT = 900° <i>celcius</i>)	48
Gambar 4.3.17	Daerah inti Las C1 (HT = 900° <i>celcius</i>)	48
Gambar 4.3.18	Daerah Haz 2 C1 (HT = 900° <i>celcius</i>)	48
Gambar 4.3.19	Daerah Haz 1 A2 (HT = 1000° <i>celcius</i>)	49
Gambar 4.3.20	Daerah inti Las A2 (HT = 1000° <i>celcius</i>)	49
Gambar 4.3.21	Daerah Haz 2 A2 (HT = 1000° <i>celcius</i>)	49
Gambar 4.3.22	Daerah Haz 1 B2 (HT = 1000° <i>celcius</i>)	50
Gambar 4.3.23	Daerah inti Las B2 (HT = 1000° <i>celcius</i>)	50
Gambar 4.3.24	Daerah Haz 2 B2 (HT = 1000° <i>celcius</i>)	50
Gambar 4.3.25	Daerah Haz 1 C2 (HT = 1000° <i>celcius</i>)	51
Gambar 4.3.26	Daerah inti Las C2 (HT = 1000° <i>celcius</i>)	51
Gambar 4.3.27	Daerah Haz 2 C2 (HT = 1000° <i>celcius</i>)	51
Gambar 4.3.28	Daerah Haz 1 A3 (HT = 1100° <i>celcius</i>)	52
Gambar 4.3.29	Daerah inti Las A3 (HT = 1100° <i>celcius</i>)	52
Gambar 4.3.30	Daerah Haz 2 A3 (HT = 1100° <i>celcius</i>)	52
Gambar 4.3.31	Daerah Haz 1 B3 (HT = 1100° <i>celcius</i>)	53

Gambar 4.3.32	Daerah inti Las B3 (HT = 1100° celcius)	53
Gambar 4.3.33	Daerah Haz 2 B3 (HT = 1100° celcius)	53
Gambar 4.3.34	Daerah Haz 1 C3 (HT = 1100° celcius)	54
Gambar 4.3.35	Daerah inti Las C3 (HT = 1100° celcius)	54
Gambar 4.3.36	Daerah Haz 2 C3 (HT = 1100° celcius)	54
Gambar 4.4.1	Hasil Pengujian Tarik <i>coil heater sample A</i>	56
Gambar 4.4.2	Grafik <i>Stress-Strain coil heater sample A</i>	56
Gambar 4.4.3	Hasil Pengujian Tarik <i>coil heater sample B</i>	57
Gambar 4.4.4	Grafik <i>Stress-Strain coil heater sample B</i>	57
Gambar 4.4.5	Hasil Pengujian Tarik <i>coil heater sample C</i>	58
Gambar 4.4.6	Grafik <i>Stress-Strain coil heater sample C</i>	58
Gambar 4.4.7	Hasil Pengujian Tarik <i>coil heater sample A1</i>	59
Gambar 4.4.8	Grafik <i>Stress-Strain coil heater sample A1</i>	59
Gambar 4.4.9	Hasil Pengujian Tarik <i>coil heater sample B1</i>	60
Gambar 4.4.10	Grafik <i>Stress-Strain coil heater sample B1</i>	60
Gambar 4.4.11	Hasil Pengujian Tarik <i>coil heater sample C1</i>	61
Gambar 4.4.12	Grafik <i>Stress-Strain coil heater sample C1</i>	61
Gambar 4.4.13	Hasil Pengujian Tarik <i>coil heater sample A2</i>	62
Gambar 4.4.14	Grafik <i>Stress-Strain coil heater sample A2</i>	62
Gambar 4.4.15	Hasil Pengujian Tarik <i>coil heater sample B2</i>	63
Gambar 4.4.16	Grafik <i>Stress-Strain coil heater sample B2</i>	63
Gambar 4.4.17	Hasil Pengujian Tarik <i>coil heater sample C2</i>	64
Gambar 4.4.18	Grafik <i>Stress-Strain coil heater sample C2</i>	64
Gambar 4.4.19	Hasil Pengujian Tarik <i>coil heater sample A3</i>	65
Gambar 4.4.20	Grafik <i>Stress-Strain coil heater sample A3</i>	65
Gambar 4.4.21	Hasil Pengujian Tarik <i>coil heater sample B3</i>	66
Gambar 4.4.22	Grafik <i>Stress-Strain coil heater sample B3</i>	66
Gambar 4.4.23	Hasil Pengujian Tarik <i>coil heater sample C3</i>	67
Gambar 4.4.24	Grafik <i>Stress-Strain coil heater sample C3</i>	67
Gambar 4.5.1	Hasil Pengujian Tarik <i>Heat Input las 3,2 kj/mm² (100A)</i>	74
Gambar 4.5.2	Hasil Pengujian Tarik <i>Heat Input las 3,84 kj/mm² (120A)</i>	75
Gambar 4.5.3	Hasil Pengujian Tarik <i>Heat Input las 4,48 kj/mm² (140A)</i>	76
Gambar 4.5.4	Hasil Pengujian Tarik <i>All Sample</i>	77