

DAFTAR GAMBAR

Gambar 1.1	Peta lokasi PT. Integrated Steel Mill	3
Gambar 1.2	<i>Steel slab</i>	3
Gambar 1.3	<i>Steel plate</i>	4
Gambar 1.4	<i>Cast & pig iron</i>	4
Gambar 1.5	Struktur organisasi PT. Integrated Steel Mill	5
Gambar 3.1	Ketidaklurusan paralel/ <i>offset (parallel misalignment)</i>	14
Gambar 3.2	Ketidaklurusan sudut (<i>angular misalignment</i>)	14
Gambar 3.3	Ketidaklurusan kombinasi (<i>Combination Misalignment</i>)	15
Gambar 3.4	<i>Pinchroll double side shear</i>	15
Gambar 3.5	<i>Scrapper pinchroll</i>	16
Gambar 3.6	Proses <i>rolling line</i>	16
Gambar 3.7	<i>Layout reheating furnace</i>	17
Gambar 3.8	<i>Finishing mill</i>	18
Gambar 3.9	<i>Layout shearing line</i>	19
Gambar 3.10	Pemotongan <i>plate</i>	19
Gambar 3.11	<i>Crop shear</i>	20
Gambar 3.12	<i>Double side shear</i>	20
Gambar 3.13	<i>Divide shear</i>	21
Gambar 3.14	Inspeksi dimensi <i>plate</i>	22
Gambar 3.15	Inspeksi bentuk <i>plate</i> baja	23
Gambar 3.16	<i>Crown</i>	23
Gambar 3.18	<i>Defect mark pinchroll</i>	25
Gambar 3.19	<i>Defect scale pinchroll</i>	25
Gambar 3.20	<i>Defect cutting chip dan burr</i>	26
Gambar 3.17	Metode <i>checksheet levelling</i> dan <i>alignment pinchroll</i>	27
Gambar 4.1	Diagram alur	28
Gambar 4.2	<i>Theodolite</i>	30
Gambar 4.3	Prisma	31
Gambar 4.4	<i>Flat level</i>	31
Gambar 4.5	<i>Micrometer inside 0-500 mm</i>	31
Gambar 4.6	Meteran	32

Gambar 4.7	<i>Clampbuckle</i>	32
Gambar 4.8	<i>Piano Wire</i>	32
Gambar 4.9	Pemasangan <i>chainblock</i>	33
Gambar 4.10	Pemasangan <i>theodolite</i>	34
Gambar 4.11	Pemasangan prisma	34
Gambar 4.12	Proses <i>levelling</i> ketinggian	35
Gambar 4.13	Proses <i>levelling</i> kemiringan	35
Gambar 4.14	Pemasangan <i>clampbuckle</i>	36
Gambar 4.15	Pemasangan <i>magnet calibration</i>	36
Gambar 4.16	<i>Calibration piano wire</i>	36
Gambar 4.17	Pengukuran <i>inside micrometer</i>	37
Gambar 4.18	Proses <i>alignment pinchroll</i>	37
Gambar 4.19	Metode <i>checksheet levelling</i> dan <i>alignment pinchroll</i>	38