

DAFTAR GAMBAR

Gambar 2.1	Contoh Penggambaran FTA.....	23
Gambar 2.2	Kerangka Pemikiran	28
Gambar 3.1	Langkah-Langkah Penelitian.....	32
Gambar 4.1	Contoh Produk Roda 2.....	37
Gambar 4.2	Contoh Produk Roda 4	38
Gambar 4.3	Dies and Tools	39
Gambar 4.4	FlowChart Proses Welding Stay 1 B65.....	40
Gambar 4.5	Stay 1 B65	40
Gambar 4.6	Diagram Pareto Jenis Cacat Stay 1 B65.....	46
Gambar 4.7	Diagram sebab akibat welding keropos.....	47
Gambar 4.8	Diagram sebab akibat welding meleset	48
Gambar 4.9	FTA Nozzle Kurang Perawatan.....	51