

DAFTAR GAMBAR

Gambar 1. 1 Data Kerusakan Mesin	3
Gambar 2. 1 <i>World Class OEE</i>	12
Gambar 2. 2 Diagram Pareto	16
Gambar 2. 3 Contoh <i>Fishbone Diagram</i>	18
Gambar 2. 4 Kerangka Pemikiran	29
Gambar 3.1 Area Produksi <i>Plywood</i>	32
Gambar 3.2 Sesi Wawancara dengan Narasumber.....	32
Gambar 3.3 Langkah - langkah Penelitian	35
Gambar 4.1 Poduk Sampoerna Kayoe	37
Gambar 4.2 Logo Sampoerna Kayoe	38
Gambar 4.3 Diagram Proses.....	41
Gambar 4.4 Pengadaan Material	43
Gambar 4.5 Lem Lapisan <i>Plywood</i>	44
Gambar 4.6 Proses <i>Veneer Rotary Cut</i>	45
Gambar 4.7 Proses <i>Glue Spreading</i>	46
Gambar 4.8 Proses <i>Cold Press</i>	47
Gambar 4.9 Proses <i>Hot Press</i>	47
Gambar 4.10 Proses <i>Cutting</i>	48
Gambar 4.11 Proses <i>Sanding</i>	49
Gambar 4.12 Grafik Hasil Perhitungan <i>Availability</i>	55
Gambar 4.13 Grafik Hasil Perhitungan <i>Performance</i>	56
Gambar 4.14 Grafik Hasil Perhitungan <i>Quality</i>	57
Gambar 4.15 Grafik Hasil Perhitungan <i>Overall Equipment Effectiveness</i>	59
Gambar 4.16 <i>Pareto Chart of Six Big Losses</i>	65
Gambar 4.17 <i>Fishbone Diagram Reduce Speed Losses</i>	67
Gambar 5.1 <i>Pareto Chart of Six Big Losses</i>	73