

DAFTAR GAMBAR

	Halaman
Gambar 1. 1 Gambar dan dimensi part rivet X	3
Gambar 2. 1 Proses <i>injection molding</i>	7
Gambar 2. 2 Cara kerja Injection Molding	8
Gambar 2. 3 Contoh Diagram Alir.....	23
Gambar 2. 4 Diagram Pareto.....	24
Gambar 2. 5 Fishbone Diagram	25
Gambar 2. 6 Contoh Check Sheet.....	26
Gambar 2. 7 Contoh Histogram	27
Gambar 2.8 Fishbone Diagram	29
Gambar 2.9 Contoh Scatter Diagram	30
Gambar 2.10 Contoh Peta Kedali.....	31
Gambar 2.11 Kerangka Pemikiran.....	53
Gambar 3.1 Langkah- langkah penelitian	58
Gambar 4.1 Contoh produk Mold.....	59
Gambar 4.2 Flow process change machine.....	61
Gambar 4.3 Gambar dan dimensi part rivet X	67
Gambar 4.4 Peta Pengendali X	76
Gambar 4.5 Peta Pengendali S	76
Gambar 4.6 Peta Pengendali S revisi 1	77
Gambar 4.7 Peta Pengendali S revisi 2	77
Gambar 4.8 Peta Pengendali S revisi 3	78
Gambar 4.9 Peta Pengendali S revisi 4	78

Gambar 4.10 Peta Pengendali S revisi 5	79
Gambar 4.11 Histogram problem proses trial	81
Gambar 4.12 Pareto diagram problem defect dimension	82
Gambar 4.13 Fishbone Diagram defect dimension.....	83
Gambar 5.1 Flow chart proses change machine sebelum perbaikan	101
Gambar 5.2 Flow chart proses change machine setelah perbaikan	102

