

DAFTAR SIMBOL DAN SINGKATAN

Singkatan / Simbol	Keterangan
RH	<i>Right/ Kanan</i>
LH	<i>Left/ Kiri</i>
VDI	<i>Verein Deutcher Ingenieure</i>
JIS	<i>Japanese Industrial Standard</i>
<i>DIN</i>	<i>Deutch Industrie Normen</i>
MPa	Mega pascal
N	Newton
N/mm^2	Newton per milimeter persegi
Pa	Pascal
N/m^2	Newton per meter persegi
F	Gaya
F_{tot}	Gaya Total
F_{Baut}	Gaya Baut
F_S	<i>Safety Factor</i>
A	Luas Penampang
AS	Luas Penampang Geser
A_{Baut}	Luas Penampang Baut
D_{Baut}	Diameter Ulir Baut
τ	Tegangan Geser
σ	Tegangan
σ_{Ijin}	Tegangan Ijin
$\sigma_{Ijin\ Baut}$	Tegangan Ijin Baut
σ_{Uts}	<i>Ultimate Strength Material</i>
σ_y	<i>Yield Strength Material</i>
σ_n	Tegangan Normal
t	Tebal pelat
L1	Panjang Pelat