

DAFTAR SIMBOL

Simbol	Keterangan
SF	<i>Single Flange</i>
DF	<i>Double Flange</i>
D	<i>Double</i>
S	<i>Single</i>
O.D	<i>Outer Diameters</i>
DZ	<i>Komatsu Type Bulldozer</i>
Wo Max	Keausan Maksimum 100%
Wo 1	<i>Worn %tage</i> Terakhir
Dt Max	Tanggal Pergantian berikutnya
Pl Max	<i>Potential Lifetime</i>
Dt1	<i>Last Replacement date</i>
Dt2	<i>Inspection Date</i>
H1	<i>Last HM Replace</i>
H2	<i>HM Inspection</i>
H3	Total <i>Lifetime</i> Komponen / Hari
H4	<i>Average</i> Jam kerja unit / hari
Mra	<i>Measure rate actual</i>
Alt	<i>Actual Lifetime</i>
Σ Mechanic	Mekanik yang bekerja.
TPB	<i>Turn Pin Bushing</i>
HM	<i>Hourse Meter</i>
S.M.R	<i>Actual Hourse meter</i>
Pit	Lokasi Tambang
KUC Master	Komatsu <i>Undercarriage Master</i> , Format File hasil pengukuran
PPU	Program Pemeriksaan <i>Undercarriage</i>
P2U	Person Pemeriksaann <i>Undercarriage</i>