

ABSTRAK

PT. CHN merupakan perusahaan manufaktur yang menghasilkan *brake system*, dan dalam perkembangannya juga memproduksi part *aluminium casting* dan *casting wheel*. Dalam melakukan proses pembuatan caliper assy front KVLP, terdapat cacat yang terjadi saat proses produksi. Untuk mengurangi cacat produksi tersebut dilakukan perbaikan pada semua faktor yang menjadi penyebab terjadinya cacat guna mengatasi penyebab masalah dengan “Analisa pengendalian kualitas cacat pada produk caliper assy front KVLP dengan metode PDCA”.

Kata kunci : Perbaikan pada semua faktor dengan metode PDCA.

PT. CHN is a manufacture company which produce brake system, and within development time forward, also produce aluminium casting part and casting wheel. In their purpose to conduct production operation for caliper assy front KVLP, there is defect it happens during production process. In order to decrease these defect in production process, there are several improvement to be done for all factors that causation the defect. Regarding the purpose to eliminate problem used “Quality control analysis of defect on caliper assy front KVLP product by PDCA method”.

Key words : Improvement in all factors by PDCA method.



UNIVERSITAS
MERCU BUANA