

## DAFTAR GAMBAR

<b>No. Gambar</b>		<b>Halaman</b>
1.1	Logo dan Produk PT. ATMPI	3
1.2	PT. Ancol Terang Metal Printing Industri	3
1.3	Lokasi PT. ATMPI	4
1.4	Struktur organisasi <i>Maintenance Departement</i>	5
3.1	Mesin <i>Feeder</i>	14
3.2	<i>Anti- Flecking System</i>	16
3.3	<i>Roll Transfer Unit Mailander 460 A</i>	17
3.4	<i>Drying Oven LTG</i>	18
3.5	<i>Stacking Rear Operator</i>	19
4.1	Alur Proses Pelaksanaan <i>Preventive Maintenance</i> di PT. ATMPI	20
4.2	Pelapisan <i>tin plate</i> polos	24
4.3	Pelapisan <i>tin plate</i> polos tanpa warna (transparan)	24
4.4	Pelapisan <i>tin plate stencil</i>	25
4.5	Pelapisan <i>tin plate spot-stencil</i>	25
4.6	Jenis-jenis <i>roll</i> karet	26
4.7	<i>Sucker cylinder</i> dan karet <i>sucker</i>	27
4.8	Pengecekan <i>timing belt</i> penggerak <i>sucker</i>	27
4.9	Lubang as <i>air cylinder rejected double sheet detector</i> yang aus	28
4.10	Pengecekan lubang as <i>air cylinder rejected double sheet detector</i>	28
4.11	Pipa angin <i>Anti-Flecking System</i>	28
4.12	Membersihkan pipa <i>Anti-Flecking</i>	29
4.13	<i>Runner pusher</i> yang aus	30
4.14	Pengecekan rel <i>runner pusher</i>	30
4.15	<i>Side-lay Coater Mailander</i>	31
4.16	Pengecekan <i>Side-lay Coater</i>	31
4.17	Pengecekan kesejajaran <i>stopper sheet</i>	32
4.18	Dudukan <i>roll Anilox</i>	32
4.19	<i>Stopper gripper</i>	33
4.20	Motor gear box pompa <i>Lacquer</i>	33
4.21	Pengecekan <i>drive drying oven</i> dan level oli <i>gear box synchron</i>	34
4.22	Tekanan angin <i>burner oven</i>	34

4.23	Pengecekan <i>filter fresh air</i>	34
4.24	Pengecekan <i>flat belt, timing belt</i> dan <i>belt pulley stacking rear operator</i>	35

