

DAFTAR TABEL

1.	Tabel 1.1	DPU <i>Painting</i> 2 periode Agustus 2017 - Januari 2018.....	2
2.	Tabel 1.2	Data cacat unit D40D.....	2
3.	Tabel 1.3	Data <i>panel area</i> cacat unit D40D.....	3
4.	Tabel 2.1	Jurnal PASTI penelitian Terdahulu	14
5.	Tabel 2.2	Jurnal Internasional penelitian Terdahulu.....	16
6.	Tabel 3.1	Tabel Kuesioner untuk operator dan pihak lain	16
7.	Tabel 4.1	Jumlah Cacat dan Total Produksi Unit D40D.....	43
8.	Tabel 4.2	Data area cacat over spray unit D40D	44
9.	Tabel 4.3	Kuesioner Kepada Operator dan Pihak Lain	44
10.	Tabel 4.4	Presentase Produk Lolos Uji.....	46
11.	Tabel 4.5	Data Area Cacat <i>Over Spray</i>	48
12.	Tabel 4.6	Data Rata-Rata Dan Presentase Cacat.....	48
13.	Tabel 4.7	Tabel Analisis 5W + 1H.....	52
14.	Tabel 4.8	Data Unit D40D Setelah Perbaiki.....	58
15.	Tabel 4.9	Data Cacat <i>Over Spray</i> Unit D40D Setelah Perbaiki	59
16.	Tabel 5.1	5W+1H.....	63