

DAFTAR GAMBAR

Gambar 1.1 <i>Flowchart</i> Kerja Praktek	6
Gambar 2.1 Logo PT. Takagi Sari Multi Utama.....	11
Gambar 2.2 Struktur Organisasi.....	14
Gambar 2.3 <i>FlowChart</i> Alur Proses Injection	20
Gambar 2.4 Bagian – Bagian Mesin <i>Injection</i>	22
Gambar 2.5 Dua Jenis Clamping Unit yang Umum Digunakan.....	23
Gambar 2.6 <i>Mold Unit</i>	25
Gambar 2.7 <i>Injection Unit</i>	26
Gambar 2.8 <i>Defect Short Mold</i>	31
Gambar 2.9 <i>Defect Flowmark</i>	32
Gambar 2.10 <i>Defect Scratch</i>	33
Gambar 2.11 <i>Defect Silver</i>	34
Gambar 2.12 <i>Defect Flashes</i>	35
Gambar 2.13 <i>Defect Contaminasi</i>	36
Gambar 2.14 <i>Defect Overcut</i>	37
Gambar 3.1 <i>Flowchart</i>	51

Gambar 3.2 Diagram Pareto.....	53
Gambar 3.3 <i>Check Sheet</i>	56
Gambar 3.4 <i>Fishbone</i>	57
Gambar 3.5 <i>Histogram</i>	59
Gambar 3.6 Diagram Batang.....	61
Gambar 3.7 Peta Kendali	62
Gambar 3.8 <i>Scatter</i>	67
Gambar 4.1 Peta Kendali P.....	73
Gambar 4.2 <i>Pareto Chart Defect Cover Crank Case</i>	78
Gambar 4.3 Diagram <i>Fishbone</i> Penyebab <i>Defect</i> Pada <i>Cover Crank Case</i>	89

