

DAFTAR TABEL

	Halaman
Tabel 1.1 <i>APU Shop Visit Summary 2019</i>	3
Tabel 2.1 Severity	20
Tabel 2.2 Detection.....	22
Tabel 2.3 Occurance	23
Tabel 2.4 Penelitian Terdahulu.....	27
Tabel 4.1 Proses <i>Rectification</i>	41
Tabel 4.2 Data Kerusakan APU	42
Tabel 4.3 Kerusakan pada APU	43
Tabel 4.4 Matriks Akar Permasalahan.....	43
Tabel 4.5 Tabel Jenis Kerusakan APU	45
Tabel 4.6 RPN dan RSV Jenis <i>Defect</i> APU	46
Tabel 4.7 <i>Why's Smoke at Exhaust</i>	50
Tabel 4.8 Rencana Perbaikan masalah <i>Smoke at Exhaust</i>	51
Tabel 4.9 Kerusakan APU sebelum <i>Improvement</i>	63
Tabel 4.10 Kerusakan APU setelah <i>Improvement</i>	63
Tabel 4.11 Rata-Rata Nilai Sigma setelah <i>Improvement</i>	64
Tabel 4.12 Kontrol dan Manfaat.....	66
Tabel 5.1 Data Kerusakan APU	69
Tabel 5.2 Jenis Kerusakan APU.....	70
Tabel 5.3 Analisa Pembahasan Penyebab <i>Smoke at Exhaust</i>	72
Tabel 5.4 Rencana Perbaikan kerusakan <i>Smoke at Exhaust</i>	73
Tabel 5.5 Usulan Perbaikan kerusakan <i>Smoke at Exhaust</i>	74