

DAFTAR GAMBAR

Gambar 1.1 Produk Bolt Head Cover Assy	2
Gambar 1.2 Produk Defect Tertinggi Mata Kunci Tidak Terbentuk	3
Gambar 2.1 Kerangka Pemikiran.....	32
Gambar 3.1 Langkah – Langkah Penelitian.....	36
Gambar 4.1 Proses Produksi Bolt Head Cover Assy	37
Gambar 4.2 Material Bolt Head Cover Assy	38
Gambar 4.3 Proses Forming.....	38
Gambar 4.4 Proses Rolling	39
Gambar 4.5 Flange Bolt	40
Gambar 4.6 Socket Bolt	41
Gambar 4.7 Bolt Head Cover Assy.....	41
Gambar 4.8 Hex Bolt	41
Gambar 4.9 Hub Bolt	41
Gambar 4.10 Hub Nut.....	42
Gambar 4.11 Hex Flange Nut	42
Gambar 4.12 Mata Kunci Tidak Terbentuk	43
Gambar 4.13 Retak.....	43
Gambar 4.14 Ulir Miring	43
Gambar 4.15 Diagram SIPOC	47
Gambar 4.16 Peta Kendali P data Atribut Produk Bolt Head Head Cover Assy Periode Agustus 2019 – Januari 2020.....	53
Gambar 4.17 Diagram Pareto.....	60
Gambar 4.18 Kriteria Defect Mata Kunci Tidak Terbentuk	61

Gambar 4.19 Diagram Tulang Ikan63

