

DAFTAR TABEL

Tabel 2.1 <i>Severity</i>	26
Tabel 2.2 <i>Occurrence</i>	27
Tabel 2.3 <i>Detection</i>	27
Tabel 2.4 Hasil penelitian FMEA PT. XYZ Tanjung Morawa Deli Serdang.....	29
Tabel 2.5 Penelitian Terdahulu Jurnal Internasional.....	31
Tabel 2.6 Penelitian Terdahulu Jurnal Nasional PASTI	33
Tabel 4.1 Data Total Produksi dan Data Jumlah <i>Defect Green tire</i> bulan April - September 2018	56
Tabel 4.2 Jenis-jenis <i>defect</i> dan deskripsi	57
Tabel 4.3 Standar visual jenis <i>defect green tire</i>	58
Tabel 4.4 Data Jenis <i>Defect</i> dan Jumlah <i>Defect Green tire</i> Bulan April – September 2018	60
Tabel 4.5 Jumlah <i>Defect Green tire</i> pada Bulan September 2018.....	61
Tabel 4.6 <i>Persentase defect Green tire</i> Bulan September 2018	62
Tabel 4.7 Kriteria <i>Defect Miss making</i> (MM) Bulan September 2018.....	63
Tabel 4.8 Jumlah <i>Defect green tire</i> bulan September 2018.....	65
Tabel 4.9 Sumbang Saran dari Karyawan.....	67
Tabel 4.10 <i>Saverity</i>	73
Tabel 4.11 <i>Occurrence</i>	73
Tabel 4.12 <i>Detection</i>	74
Tabel 4.13 FMEA <i>Defect Miss making</i> (MM) <i>Jointless</i> ketarik.....	75
Tabel 5.1 Rangking RPN untuk Masing-masing <i>Mode</i> Kegagalan	80
Tabel 5.2 Rencana dan Tindakan Perbaikan Kualitas (5W+1H)	84
Tabel 5.3 Hasil Perbaikan	97
Tabel 5.4 Standarisasi Perbaikan	98
Tabel 5.5 Data jumlah <i>Defect Miss Making</i> (MM) bulan September 2018.....	100
Tabel 5.6 Data Kriteria <i>Defect Miss Making</i> (MM) bulan September 2018.....	101
Tabel 5.7 Data jumlah <i>Defect Miss Making</i> (MM) bulan November 2018	102
Tabel 5.8 Data Kriteria <i>Defect Miss Making</i> (MM) bulan November 2018.....	102