

DAFTAR GAMBAR

Gambar 1.1	Presentasi <i>Downtime</i> Bulan Juni 2018.....	2
Gambar 2.1	Pilar TPM.....	7
Gambar 2.2	<i>Overall Equipment Effectiveness</i>	19
Gambar 2.3	Diagram Sebab Akibat.....	24
Gambar 2.4	Diagram Kerangka Pemikiran.....	31
Gambar 3.1	Diagram Alir Penelitian.....	35
Gambar 4.1	Alur Produksi.....	41
Gambar 4.2	BS Tidak Standar.....	43
Gambar 4.3	BS Bubble.....	43
Gambar 4.4	Bagian Depan Mesin Oven.....	44
Gambar 4.5	Bagian Depan Mesin Oven.....	45
Gambar 4.6	Tungku Pengapian Mesin Oven.....	45
Gambar 4.7	Monitor Aktivasi Mesin Oven.....	46
Gambar 4.8	Tabung Adonan.....	46
Gambar 4.9	Baking Plat Yang Lengket.....	47
Gambar 4.10	Pembersihan Baking Plat.....	48
Gambar 4.11	Proses Chrome.....	48
Gambar 4.12	<i>Chain Link</i> Patah.....	49
Gambar 4.13	<i>Chain Link</i> Patah.....	50
Gambar 4.14	<i>Chain Link</i> Patah Dengan Posisi Baking Plat Terbuka.....	50
Gambar 4.15	Mesin Oven.....	51
Gambar 4.16	Kecenderungan Nilai Availability Ratio Juli-September 2018.....	61
Gambar 4.17	Kecenderungan Nilai <i>Performance</i> Juli- September 2018.....	63
Gambar 4.18	Kecenderungan Nilai <i>Quality Ratio</i> Juli – September 2018.....	65
Gambar 4.19	Kecenderungan Nilai OEE bulan Juli – September 2018.....	67

Gambar 5.1	Grafik Hasil Perhitungan <i>Availability</i> Juli – September 2018.....	78
Gambar 5.2	Grafik Hasil Perhitungan <i>Performance</i> Juli - September 2018	79
Gambar 5.3	Grafik Hasil Perhitungan <i>Quality</i> Juli-September 2018	80
Gambar 5.4	Grafik <i>Overall Equipment Efectiveness</i> Juli-September 2018	82
Gambar 5.5	Fishbone Diagram Penyebab Rendahnya Nilai OEE	83
Gambar 5.6	Diagram Pareto <i>Six Big Losses</i>	86

