

## DAFTAR GAMBAR

Struktur Gedung Hokuriku dan Soil Profile .....	II-3
Kegagalan Tiang Pancang Gedung NHK .....	II-4
Denah titik Tes Bored .....	II-6
Borlog BH-1 .....	II-7
Borlog BH-1 hal 2 .....	II-8
Borlog BH-2 .....	II-9
Borlog BH-2 hal 2 .....	II-10
Borlog BH-3 .....	II-11
Borlog BH-3 hal 2 .....	II-12
NSPT vs Depth .....	II-14
Berat isi dan angka pori .....	II-15
Triaxial kohesi vs sudut geser .....	II-16
Direct Shear Test .....	II-17
Peta Gempa respon spectrum 0.2 det .....	II-18
Peta Gempa respon spectrum 1 det .....	II-19
Tahap penelitian .....	III-2
Flowchart perhitungan .....	III-3
Zona likuifaksi .....	IV-2
Profil tanah .....	IV-3
Grafik CN vs Tegangan efektif tanah .....	IV-6
Tegangan Efektif ( $P_o'$ ) .....	IV-7
Dutch Cone Penetration Test .....	IV-8
Diagram Faktor Reduksi, CSR, CRR, FS .....	IV-10
Pondasi P-4 saat terjadi likuifaksi .....	IV-23