

DAFTAR GAMBAR

No. Gambar	Halaman
1.1 Logo PT. Pertamina	3
1.2 <i>Organization Structure Refinery Unit III Plaju</i>	8
1.3 <i>Organization Structure Maitenance Execution</i>	10
1.4 <i>Organization Structure Workshop Maintenance Execution</i>	11
1.5 <i>Prosedur Perbaikan Equipment</i>	13
3.1 <i>Konduksi Aliran Panas</i>	19
3.2 <i>Konveksi Aliran Panas</i>	20
3.3 <i>Radiasi Aliran Panas</i>	21
3.4 <i>Chiller</i>	22
3.5 <i>Cooler</i>	22
3.6 <i>Condensor</i>	23
3.7 <i>Heat Exchanger</i>	23
3.8 <i>Reboiler</i>	24
3.9 <i>Tube Steel dan Tube Brass</i>	25
3.10 <i>Shell</i>	26
3.11 <i>Jenis Shell Plutting</i>	27
3.12 <i>Jenis-Jenis Cover Plutting</i>	27
3.13 <i>Baffle Plate</i>	28
3.14 <i>Fixed TubeSheet</i>	29
3.15 <i>Floating TubeSheet</i>	29
3.16 <i>Spacer</i>	30
4.1 <i>Diagram Alir Alur Proses</i>	31
4.2 <i>Permukaan Tube Terdapat Physical Damage</i>	34
4.3 <i>Shell Terdapat Cracked Dan Broken</i>	34
4.4 <i>Pemeriksaan Baffle Plate</i>	35
4.5 <i>Pemeriksaan Pada Tie Rod Dan Spacer</i>	35
4.6 <i>Pemeriksaan Pada Tube Sheet</i>	36
4.7 <i>Prosedur Order Material</i>	37